

	MA'ADEN ALUMINIUM COMPANY	DoC. Ref:
	<b>JOB QUALIFICATION PROGRAM</b> <b>(JQP)</b>	Issue: Date Effective: Page 1 of 2

Employee Name:	<u>Salim M. Al-Shehri</u>	Employee ID:	<u>5018737</u>
Grade:	<u>SA08</u>	JQP Level:	<u>5</u>
Job Title:	<u>Mechanical Technician</u>	Date of Report:	<u>Mar 11, 2016</u>
Supervisor name:	<u>Hamad M. Al-Marri</u>	Supervisor ID:	<u>5017999</u>

Areas worked in
Smelter - Reduction <span style="color: gray;">This portion is to be filled by immediate supervisor</span>
Equipment's worked at
PTA-05 (4231-MJKT-0005) <span style="color: gray;">Employee to fill this portion</span>
Problem solved
PTA-5 air compressor tripping on auto condensate drain alarm.
Actions Taken
Cleaned the becomat valve. Run the compressor.  <span style="color: gray;">Employee to fill this portion</span>

 	MA'ADEN ALUMINIUM COMPANY	DoC. Ref:
	<b>JOB QUALIFICATION PROGRAM</b>  <b>(JQP)</b>	Issue:  Date Effective:  Page 2 of 2

Technical Explanation of the Spares Utilized and it value to the equipment
There are no spare parts were used, due to cleaning the exist valve only. Employee to fill this portion
5 whys of the problem
Hot weather condition. Air dryer doesn't working properly. Employee to fill this portion and use 5 whys method to get to recommendation
Recommendations
Employee to fill this portion
Recognized Hazards
Pressured air in the line. Fumes from the pot cells. Employee to fill this portion
Corrective actions for hazards
Releasing the pressured air from the line. Wearing the respirator. Employee to fill this portion

#### Acknowledgement

Supervisor Name	ID	Signature
Hamad M. Al-Marri	5017999	
Area Engineer	ID	Signature